

# Part Change Notification:

Dear valued customer, please be advised that the part number(s) listed in the table below have undergone a change that may impact form, fit, function, or material. A detailed breakdown of this change is provided within this document.

## Affected Part Number(s):

A7A-USB2C-1-B
A7B-USB1C-1-B
A7B-USB2C-1-B
A8-USB2-1-B-4.8A-T
A8-USB2-1-B-4.8A
A8-USB2-1-BN-4.8A
A8-USB1-1-BN-2.4A
A6-USB2C-1-B

## **Detailed Description of Change:**

Both terminals will now be provided with nickel plating. Previously only the negative terminal had such plating. This change will improve corrosion resistance of the part. During a 200hr salt spray test, the terminal without plating experienced significantly more corrosion. By including the plating on both terminals, the corrosion resistance of the part will be increased without negatively impacting the functionality.

## **Effective Date: 09/04/2025**

\*Please note that parts using the original specifications may still be provided as Switch Components works off the stock that it has on hand.


If you have any questions regarding this change, please contact Switch Components at sales@switchcomp.com or reach out to your local sales rep for further details.

Issued By: Samuel Kenny Role: Product Manager

Signed: Samuel Kenny

# Appendix:

1. Finished Product Appearance Change:



2. 200 Hour Salt Spray Corrosion Testing:

